

# 2015 Annual Report for Hazardous Waste Exports

40 CFR § 262.56

Title 22 CCR § 66262.56

TAMCO

12459-B Arrow Route

Rancho Cucamonga, CA 91739

February 2016



**GERDAU**

## **1.0 EXPORTER INFORMATION**

TAMCO is a steel mini-mill that recycles ferrous scrap metal into concrete reinforcing bars (rebar). Mini-mills use electric arc furnace technology to melt scrap steel into semi-finished steel billets. These billets are then reheated and processed in a rolling mill where they are made into a wide variety of rebar lengths, sizes and grades.

TAMCO recycles over 500,000 tons of steel a year. This steel comes from junked cars, appliances, tin cans, used oil filters and industrial scrap. More steel is recycled in the United States than glass, aluminum, paper and plastic combined. Several years ago, TAMCO began accepting used oil filters (drained and crushed) for recycling into rebar. For every ton of used oil filters the company recycles, ten cubic yards of landfill are conserved and thirty-one gallons of motor oil is kept from landfills and oceans.

TAMCO captures dust emissions from the melting process with an efficient baghouse, thus keeping the dust from entering the atmosphere. Once the dust is captured, the iron, zinc, lead and cadmium in the dust is recycled, which reduces the amount of material that goes to hazardous waste landfills.

### **1.1 EPA Identification Number**

CAD982361404

### **1.2 Facility Name**

TAMCO

### **1.3 Mailing Address:**

P.O. Box 325

Rancho Cucamonga, CA 91739

### **1.4 Site Address:**

12459-B Arrow Route

Rancho Cucamonga, CA 91739

## **2.0 CALENDAR YEAR OF REPORT**

2015

Gerdaul – Rancho Cucamonga Mill – [www.gerdau.com/longsteel](http://www.gerdau.com/longsteel)

12459 Arrow Rte, Suite B – PO Box 325 – Rancho Cucamonga, CA – 91739 – Phone: 909-899-0660 – Fax: 909-899-1910

2



### 3.0 CONSIGNEE INFORMATION

#### 3.1 EPA Identification Number

TXR000047670

#### 3.2 Facility Name

Zinc Nacional S.A.

#### 3.3 Mailing Address:

c/o VDC Corporation  
3104 Chelo Street & Highway 57  
Eagle Pass, TX 78852

#### 3.4 Site Address

Serafin Pena, 938 Sur  
Monterrey, Nueva Leon, Mexico

### 4.0 HAZARDOUS WASTE INFORMATION

#### 4.1 Description

Baghouse dust captured from the process of recycling steel with an electric arc-furnace.

#### 4.2 EPA Federal Hazardous Waste Code

K061 – Emission control dust/sludge from the primary production of steel in electric furnaces.

#### 4.3 California Hazardous Waste Code

591 – Baghouse waste

#### 4.4 DOT Hazard Class

DOT Hazard Class 9 – Miscellaneous

#### 4.5 Transporter Information

*4.5.1 Burlington Northern Santa Fe Railway Company*  
3001 Lou Menk Drive  
Forth Worth, TX 76131-2815  
EPA ID Number: MND048341788  
ATTN: David Rodriquez

Gerda - Rancho Cucamonga Mill - [www.gerdau.com/longsteel](http://www.gerdau.com/longsteel)

#### 4.5.2 *Kansas City Southern Railroad*

1610 Woodstead Court  
The Woodlands, TX 77380  
EPA ID Number: NOD006965859

#### 4.5.3 *Kansas City Southern Mexican Railway Company*

Monterrey, Mexico  
Kansas City Southern de Mexico, S.A. de C.V.  
Manuel L. Barragan No. 4850 Nte.  
Col. Hidalgo  
C.P. 64420  
EPA ID Number: None

### 4.6 **Waste Shipments**

For calendar year 2015, baghouse waste export shipment were 10,186,352 pounds (5,093 tons) in a total of 57 shipments.

**Table 1 – Annual Waste Exported**

<b>Year</b>	<b>Pounds of Baghouse Dust Exported</b>
2015	10,186,352

## 5.0 **WASTE REDUCTION EFFORTS**

### 5.1 **Efforts Undertaken to Reduce the Volume and Toxicity of Waste**

#### 5.1.1 *Reduction in Volume*

Manufacturing steel from recycled steel represents a significant reduction in waste. Annual steel recovery efficiency average is 98.4%. Waste shipments are for additional recycling by metal recovery which continues to **represent** additional waste volume reductions.

#### 5.1.2 *Reduction in Toxicity*

Inspections of incoming recycled steel continue at the facility preventing the introduction of unwanted materials. No changes can be expected in the Toxicity Characteristics of the baghouse dust.

Gerdaul – Rancho Cucamonga Mill – [www.gerdau.com/longsteel](http://www.gerdau.com/longsteel)



## 5.2 Description of Changes in the Volume and Toxicity of Waste Actually Achieved During the Year in Comparison to the Extent Such Information is Available for Years Prior to 1984

Data is not available in years prior to 1984. Current recovery efficiency is stable at an average of 98.5% for the last ten years.


**Table 2 Annual Recycle Rate**

Year	Pounds of Baghouse Dust	Pounds Produced	Recycle Rate %
2006	14,566,200	1,002,040,00	98.6%
2007	12,720,400	861,392,000	98.5%
2008	14,680,00	886,964,000	98.4%
2009	3,751,600	276,996,000	98.7%
2010	6,096,950	436,988,000	98.6%
2011	6,780,250	409,860,000	98.4%
2012	9,513,530*	671,750,000	98.6%
2013	8,981,020	584,906,000	98.5%
2014	10,354,500	721,871,800	98.6%
2015	10,186,352	625,572,000	98.4%
Average			98.5%

*\*2012 Pounds of Baghouse Dust for Recycle Rate calculation includes shipments to domestic locations.*

## 6.0 CERTIFICATION BY EXPORTER

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fine and imprisonment.



---

Mr. Mark Olson  
VP/General Manager



ROM:

TAMCO

12459-B Arrow Route

Rancho Cuernavaca, CA 91739

5169 02 028  
The information on this label is for informational purposes only. It is not intended to be used as a substitute for professional advice. The information is provided as a service to the public and is not a guarantee of performance. The information is provided as a service to the public and is not a guarantee of performance. The information is provided as a service to the public and is not a guarantee of performance.



SEE NOTE ON REVERSE FOR LIMITS OF LIABILITY. The information on this label is for informational purposes only. It is not intended to be used as a substitute for professional advice. The information is provided as a service to the public and is not a guarantee of performance. The information is provided as a service to the public and is not a guarantee of performance. The information is provided as a service to the public and is not a guarantee of performance.



7015 1730 0000 1201 0792

MAR 2 1978

TO:

International Compliance 2254A EPA

1200 Pennsylvania Ave, NW.

Washington, DC 20460

Route EPA Mail

To: International Compliance

Assurance Division

Mailstop: ARIEL RIOS NORTH

Department: 2254A

Certified

